

John Roberts House  
Carter Farm  
Gatesville vicinity  
Gates County  
North Carolina

HABS No. NC-34

HABS  
NC  
37- GATV.V,  
2-

PHOTOGRAPHS  
WRITTEN HISTORIC AND DESCRIPTIVE DATA  
District of North Carolina

Historic American Buildings Survey

Prepared at Washington Office  
for Southeast Unit

HABS  
N.C.

37. GATV.V

2-

JOHN ROBERTS HOUSE  
Carter Farm  
Gatesville vicinity, Gates County, North Carolina

Owner: J. N. Carter

Date of erection: Early eighteenth century

Present condition: Poor

Description:

Frame; story and a half; gable roof; end chimney, rebuilt in common bond. No windows in end elevation except one in gable. Long elevations identical, one door and one window. Sash missing, was probably 9/9. Doors in very bad condition but are richly paneled with eight raised panels and framed by full architraves.

Interior: one large room with paneled dado and overmantel. Stair, ascending at left of fireplace in the corner, paneled in about nine risers up, with a door. The post is square with a moulded handrail, the balusters missing. They were square in section, set diagonally and very close together on a closed stringer.

Author: TW

Approved: 9/1/42